

Fig. 1




Fig. 2




Fig. 3



Fig. 4





Fig. 5



[illegible]

Fig. 6




Fig. 7





Fig. 8



CONTACT BETWEEN THE GROOVE OF THE
HOUSING AND THE OUTER ROLLER AT THE
OPPOSITE SIDE OF THE LOADED SIDE

Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




FIG. 14

Fig. 14




Fig. 15




Fig. 16





Fig. 17






Fig. 19

